

Message:

Two recent inspections found cracks at the hub. One was right through the added side plate the other could only be seen from underneath. Have your folks take a close look.

Jos D Gallagher
Program Manager 1
New York State, Dept of Labor
Industry Inspection Bureau
518 457 1212









