

# NAFLIC

*National Association For Leisure Industry Certification*

Standards & Related Documents Committee

TECHNICAL BULLETIN — AUGUST 2008

## 352. Octopus Centre Stub Shaft Defect

The committee has been informed of the following crack found on the centre stub shaft from a Hayes Fabrications Octopus ride. The shaft supports and aligns the inner and outer rotating poles of the ride centre.

This was the first time the shaft had been inspected since it was manufactured circa 1964. This demonstrates the importance of ensuring the shaft is disassembled from the ride in order to facilitate NDT. It was noted that the component was particularly difficult to remove from the device. Controllers and Registered Inspection bodies are reminded of the requirements of paragraph 137 in Fairgrounds and amusement parks Guidance on Safe Practice (HSG 175).



C Committee Members:- Mr. R Nicholls(Chairman), Mr. Peter Smith,  
Mr. John Green, Mr. Phil Mitchell, Mr. Ron Dale, Mr. Mark Wolstenholme, Mr. Graham Dockerty & Mr. David Inman  
© August 2008

PO BOX 752, SUNDERLAND, SR3 1XX

TEL & FAX: (0191) 5239498

standards@naflic.org.uk



C Committee Members:- Mr. R Nicholls(Chairman), Mr. Peter Smith,  
Mr. John Green, Mr. Phil Mitchell, Mr. Ron Dale, Mr. Mark Wolstenholme, Mr. Graham Dockerty & Mr. David Inman  
© August 2008

PO BOX 752, SUNDERLAND, SR3 1XX TEL & FAX: (0191) 5239498  
standards@naflic.org.uk