

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — JUNE 2008

353. Contact with manufacturers regarding bulletins

There have been some instances recently where manufacturers' bulletins have not been sent to the controller. Clearly, when the device is on a fixed location the manufacturer should know where to send the bulletin, however, as travelling devices change ownership or controllers change postal address', the line of communication can be lost.

It is recommended that all controllers establish contact with the manufacturer (where possible) and request any relevant bulletins.

There are numerous websites that regularly post bulletins on the Internet, links to many of these sites can be found on http://www.ltc.co.uk/LTC_Ride_Technical_Bulletins.htm.