

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — AUGUST 2008

351. Safeco Frog Restraint Cracks

The committee has been informed of the following cracks on a Safeco Frog ride.

These areas should be part of the periodic and documented visual inspection by the controller as well as the annual inspection by the Registered Inspection Body as required by paragraph 192 of Fairgrounds and amusement parks Guidance on Safe Practice (HSG 175).



C Committee Members:- Mr. R Nicholls(Chairman), Mr. Peter Smith,
Mr. John Green, Mr. Phil Mitchell, Mr. Ron Dale, Mr. Mark Wolstenholme, Mr. Graham Dockerty & Mr. David Inman
© August 2008

PO BOX 752, SUNDERLAND, SR3 1XX

TEL & FAX: (0191) 5239498

standards@naflic.org.uk